

# “X-Stream” Restoration



^ Installing erosion mat

The bank of Baugo Creek, near Baugo Station, has been eroding away a few inches each year since the park opened in 1987. In the spring of 2007, we restored the bank to slow future erosion.

A series of terraces were installed with a rock base. Boulders were strategically placed along the shoreline to reduce the creek's ability to undercut the bank. These rocks will also provide habitat for insects and fish.

The banks were seeded with a mix of native grasses such as big and little bluestem. Red osier dogwood saplings will secure the bank as they grow.



^ Little Bluestem

Red Osier Dogwood >



Funding for this project was provided by:



## You Can Help!

Please help our stream restoration be successful by keeping off the banks so the plants can grow.

Special thanks to JF New for their assistance with this project.